?5 <b>6-11.6-</b> R <b>eferenc</b>	e: Telephone conver	Ris-6 redio equ	y-seven (l:7) defec	: <b>tive</b> 25X
	e: Telephone conver	Ris-6 redio equ		: <b>tive</b> 25X
Roferenc			<del>-</del>	
		aution between	of this Agency	of 25X
	15 February 1954			•
being be 2. required ment. E dates th	os. 2063 through 339 Id by this Agency at The subject contract to repair these min nclosed herewith is ey were shipped by t the dates they were En incering Division	ttor does not beli steen (19) units a list of the units the Inspector of he inspected by the	eve that he shoul at no cost to the its in question and leval Material from	i be Ogvern- d the Chicago
and Insp Division returnix 1951 by repaired seven (1	This past 3 June 19  a Engineering Enginee	), Testing and Division/OC (	e Evaluation Section   and Adm   agreed that Endie units here in the was advised 15   the may mad approximate	instration 25X 25X 11su of 1su of 25X 25X 25X 25X
in abeys rep <b>air</b> c	In view of the above mee pending advice for replacement of the sould not be repaired	from Engineering on nineteen (19) u	Division/OC, regar	ding the
	es: List of units in quitement of June 1953	mestion.		25X1
LO/PD/	IB/J(19 Febre	ary 19丸)		
D <b>istri</b> lo Ori	tion: 0 % 1 - Addresses 1 - ASC-148-1877 1 - Chrono 1 - T & E/OC	1 - Sup	ply Division	

Sanitized Copy Approved for Release 2011/09/20 : CIA-RDP78-03424A002400020049-2

## Contract /SC-148 Defective Esterial

Date Shipped by INN, Chicago	Serial Number	Date Inspected by T & E Section/OC	Description of Defects
5-28-53	2063	7-13-53	Intermittent W-R tube in RA unit-hi attenuation @15mc
5-26-53	2127	7-13-53	Defective crystal salibration
5-28-53	2133	7-13-53	Defective leading switch
1-15-53	2597	5-13-53	Bad hum in receiver
. •	2700	5-13-53	Low sensit'vity in receiver
	2722	5-13-53	Voltage regulator tube shorted internally
	2784	5-11-53	Intermittant AC power plage
••	2856	5-11-53	Excessive signal attenuation Orem antennes
	2889	5-18-53	HFO became inoperative during
5-26-53	3026	52753	Failure of emphones (Telex)
6-2-53	3086	7-13-53	Low output 7 mc on Hi bend
6-12-53	3090	7-15-53	Receiver insensitive above 14.8 mg
6-12-53	3172	7-15-5)	Receiver defective, transmitter
6-30-53	3265	7-15-53	Transmitter has intermittent autennes loading switch
6-12-53	3295	7-15-53	Transmitter has low output on hi band
6-12-53	3303	7-15-53	Tuning dial defective
6-18-53	3367	7-15-53	Receiver intermittant on both
6-19-53	3 <b>39</b> 0	?-15-53	No .BF) in receiver
6-19-53	3396	7-15-53	Insulation on power supply cord term

Sanitized Copy Approved for Release 2011/09/20 : CIA-RDP78-03424A002400020049-2



C IDENTIAL SECRET

Sanitized Copy Approved for Release 2011/09/20 : CIA-RDP78-03424A002400020049-2

UNCL	ASSIFIED RESTRICTED C ID	ENTIAL AND BOTTOM	SECRET)			
UNCLASSIFIED RESTRICTED C IDENTIAL (SENDER WILL CIRCLE CLASSIFICATION TOP AND BOTTOM)						
	CENTRAL INTELLIGENCE A	GENCY				
	OFFICIAL ROUTING					
		11/11				
TO	,	INITIALS	DATE			
!	Okiel Paralne					
2	Okief 19010e	96/B	2-26			
3	T.H.S.	٧				
4						
5						
FROM		INITIALS	DATE			
	Olief, Colories O. layer Br 1 Polls		<u> </u>			
2						
3						
	APPROVAL INFORMATION  ACTION DIRECT REPLY  COMMENT PREPARATION OF R  CONCURRENCE RECOMMENDATION	REPLY -	SIGNATURE RETURN DISPATCH FILE			
REI	MARKS: 2-3. When you eaction to this let's nogether and prepare	septen of	tarvey's temporary			
E C	RET CONFIDENTIAL RESTRICTE	ED HNGI	.ASSIFIFD			

25X1